



DISPOSITIVI DI MESSA A TERRA E CORTO CIRCUITO PER LINEE AEREE

EARTHING AND SHORT CIRCUIT DEVICES FOR OVERHEAD CABLES

	codice IW <i>IW code</i>	Icc (kA / 1s) <i>Icc (kA / 1s)</i>	descrizione	<i>description</i>	conf. <i>pack.</i>
	MT-6613	8	<ul style="list-style-type: none"> • 3 pinze ad armamento preliminare MT-613 • cavi di collegamento 35 mm², scarto max tra le pinze: 2,75 m • 1 piatto porta-pinze MT-635/1-C • 1 bobina con corda rame 16 mm², L= 16 m • 1 sacca di trasporto M-87295 • fioretto consigliato: CE-4-21-C • per conduttori Ø 5-30 mm 	<ul style="list-style-type: none"> • 3 cocking pliers preliminary MT-613 • connection cables 35 mm², max gap between clamps: 2.75 m • 1 MT-635/1-C collet holder plate • 1 coil with 16 mm² copper rope, L= 16 m • 1 transport bag M-87295 • suggested stick: CE-4-21-C • for cable section Ø 5-30 mm 	1
	MT-6613/1	17,5	<ul style="list-style-type: none"> • 3 pinze ad armamento preliminare MT-613 • cavi di collegamento 95 mm², scarto max tra le pinze: 2,75 m • 1 piatto porta-pinze MT-635/1-C • 1 bobina con corda rame 35 mm², L= 15 m • 1 morsa di terra MT-840/1 • 1 sacca di trasporto M-87295 • fioretto consigliato: CE-4-21-C • per conduttori Ø 5-30 mm 	<ul style="list-style-type: none"> • 3 cocking pliers preliminary MT-613 • connection cables 95 mm², max gap between clamps: 2.75 m • 1 MT-635/1-C collet holder plate • 1 coil with 35 mm² copper rope, L= 15 m • 1 MT-840/1 earth clamp • 1 transport bag M-87295 • suggested stick: CE-4-21-C • for cable section Ø 5-30 mm 	1
	5DI2001	12,7	<p>DISPOSITIVO MOBILE DI MESSA TERRA E CORTO CIRCUITO DI LINEE AEREE AT</p> <ul style="list-style-type: none"> • 3 pinze di contatto. • 3 cavi di collegamento, in rame extraflessibile che collegano le pinze ai morsetti di terra. • sezione: 50 mm² – L = 6 m • 3 morsetti di terra a serraggio manuale • cassetta metallica di trasporto • fioretto componibile da 4,5 metri in due pezzi e sacca di trasporto 	<p>MOBILE EARTHING AND SHORT CIRCUIT DEVICE OF OVERHEAD LINES</p> <ul style="list-style-type: none"> • 3 contact clamps. • 3 connection cables, in extra-flexible copper that connect the clamps to the earth terminals. • section: 50 mm² – L = 6 m • 3 manually tightened earth terminals • metal transport case • 4.5 meter modular stick in two pieces and transport bag 	1